

# General Environmental Incident Summary

**Incident:** 3358      **Date/Time Notice:** 6/18/2014      1810      **DEM Incident No:**  
**Responsible Party:** David Low  
**Date Incident:** 6/15/2014      **Time Incident:** 0330      **Duration:** 1 hours  
**County:** McKenzie      **Twp:** 152      **Rng:** 95      **Sec:** 25      **Qtr:**  
**Lat:** 47.96198      **Long:** -102.77280      **Method:** Interpolation from map  
**Location Description:** EOG Hawkeye 100-2501H. From New town, ND drive 9 miles west on Highway 23, turn south on county road 27 for one mile to well location.  
**Submitted By:** Mark Glaser      **Affiliation:** Targa  
**Address:** 1939 125th Ave NW  
**City:** Watford City      **State:** ND      **Zip:** 58854

## Received By:

**Contact Person:** David Low  
1939 125th Ave NW  
Watford City, ND 58854

**Distance Nearest Occupied Building:** 1200 Feet      **Release Contained:** No

**Type of Incident:** Pipeline Leak

**Description of Released Contaminant:** crude oil

**Volume Spilled:** 180.00 barrels      **Ag Related:** Yes

**EPA Extremely Hazardous Substance:** No      **Reported to NRC:** Yes

## Cause of Incident:

A one inch valve broke off of the pipeline where it exited the LACT building.

## Risk Evaluation:

None

**# of Fatalities:** 0      **# of Injuries:** 0      **Affected Medium:** 03 - soil

## Potential Environmental Impacts:

Soils were impacted from oil saturation.

## Action Taken or Planned:

Pipeline was shut in, Vac truck was immediately dispatched to remove free oil liquid. Impacted soils are being excavated and removed. No impacts to surface water.

Report was originally sent to NRC 6/15/2014 at 0520.

**Wastes Disposal Location:** An approved disposal site will be utilized.

**Agencies Involved:** NDDH, MHA, BIA

## ***Updates***

---

***Date:*** 6/18/2014

***Status:*** Reviewed; BIA/Tribal Lead

***Staff:*** Roberts, Kris

***Updated Volume:***

***Notes:***

Release from a pipeline leak, due to a broken valve, appears to have remained on an oil well site. Report is forwarded to MHA Environmental, BIA, and EPA.